

HISTORIC PRESERVATION ASSISTANCE PROJECT

Strafford Rockingham Regional Council

1 Water Street, Exeter, New Hampshire


Phone: (603) 778-0885

| | | |
|--|--------------------|---|
| TOWN: Kingston | COUNTY: Rockingham | UTM: Z 19 /E 330900 /N4752300 |
| SURVEY NUMBER: 53 | | USGS QUAD: Haverhill Quad 15' series |
| COMMON NAME: The Mahone House | | FUNCTIONAL TYPE: Dwelling |
| HISTORIC NAME: John Goodwin House | | PRESENT USE: Residential |
| LOCATION: W. side Rt. 125, .85 Mi. N Inter- section Rt. 125 & old Mill Road | | ARCHITECT/BUILDER: Unknown |
| OWNER: William E. Mahone | | CONDITION: Exc. <u>Good</u> Fair <u>X</u> Poor <u>Ruins</u> |
| ADDRESS: #164 Rte 125, Kingston, NH | | INTEGRITY: Original Site <u>X</u> Moved <u> </u> (When: <u> </u>) |
| MAP & PARCEL #: R21-20 | | Major alterations & date: Asbestos shingle siding added, date unknown |
| DATE: C. 1880 | | LEVEL/SIGNIFICANCE: Natl <u>State</u> Local <u>X</u> |
| SOURCE: Assessors Office Kingston | | |
| STYLE: Vernacular Cape | | |

GENERAL DESCRIPTION: Structural System

1. FOUNDATION: Stone X Brick Concrete Concrete Block
2. WALL STRUCTURE: Wood Frame Post & Beam Ballon Frame Other
Load Bearing Masonry Stone Brick Concrete Block Other
Metal Iron Steel Other
3. WALL COVERING: Clapboard Wood Shingle Board & Batten Shiplap Aluminum
Novelty Stucco Stone Brick Sheet Metal Asphalt Shingles Vinyl
Asphalt Sheeting Composite Board Other Asbestos
4. ROOF SHEATHING: Wood Shingle Asphalt Shingle Standing Seam Tim Slate
Pressed Metal Sheet Metal Rolled Asphalt Other
5. ENGINEERING STRUCTURE:
6. OTHER:
of Stories 1 1/2 # of Bays 5 X 2 Approx. Dimensions 34' X 24'
Roof Style: Gable X Hip Gambrel Flat Shed Mansard Jerkinhead
Monitor Sawtooth Other
Appendages: Porches Towers Dormers Bay Windows Ells Chimneys 1
Wings Cupolas Sheds 1 Garage 1 Other
Entry Location: Center X Sidehall Other

MAP (Indicate North in circle):



PHOTO



Description of View:

Front (F) Side (N)

Photographer: Herb Bubert

Negative with: S.R.R.C.

Negative File Number: H-20-0-0/23-23A

ADDITIONAL ARCHITECTURAL AND STRUCTURAL DESCRIPTION:

The Mahone house is a 1½ story cape built in the late nineteenth century, which has been altered by later additions including the application of asbestos shingle siding. The center entry door has four panels and one large light.

All of the windows are recent with two over two and one over one sash. The medium pitched roof is topped by a concrete block chimney and the roofline has a boxed cornice with a wide moulding applied below the lateral eaves. A shed dormer is located on the west elevation. The house rests on a fieldstone foundation. A 1 story, gable roofed wing projects to the south. It has two over two windows, a new 4 panelled door with one large light, and a concrete block foundation and walls.

RELATED STRUCTURES AND CONTEXT: There is an attached 1 story, gable roofed garage located to the south of the main block.

BOUNDARY AND ACREAGE DESCRIPTION: 6.7 Acres. Bounded on the N. by Rocky Hill Realty, and Battles Garage, S. by Fabrizio and Rogers, W. by Nason, E. by Rt. 125.

REFERENCES:

1892 Map Mrs. John Goodwin

STATEMENT OF SIGNIFICANCE (Evaluation & Historical Associations):

The Goodwin House has no aspirations to any particular style.

Map Data: 1892: Mrs. John Goodwin

SURROUNDING ENVIRONMENT: Open Land ☐ Woodland ☐ Scattered Bldgs ☐ Moderately Built Up ☐
Densely Built Up ☐ Residential ☐ Commercial ☐ Industrial ☐ Agricultural ☐
Roadside Strip Development ☐ Other ☐

Recorded By: H. Bubert, S. Novak

Date: 2/15/80

