

CULTURAL RESOURCES SURVEY FORM

TOWN: Kingston COUNTY: Rockingham

SURVEY NUMBER: 154A

COMMON NAME: Dunbar House

HISTORIC NAME: A. C. Chase House

LOCATION: Off Little River Rd. at Rte 125

OWNER: Richard & Irene Dunbar
3 Rte 125 Access Road
ADDRESS: Kingston, NH

MAP & PARCEL#: R-34 43

DATE: c. 1895
SOURCE: Inspection

STYLE: Late 19th century Vernacular

UTM: Z /E /N

USGS QUAD:

FUNCTIONAL TYPE:

PRESENT USE: Residence

ARCHITECT/BUILDER: Unknown

CONDITION: Exc ___ Good x Fair ___ Poor ___ Ruins ___

INTEGRITY: Original Site ___ Moved x
Date 1950

Major Alterations & Date:
Moved when junction Routes 125+111
rebuilt in 1950's

LEVEL/SIGNIFICANCE: Natl ___ State ___ Local ___

BOUNDARY AND ACREAGE DESCRIPTION: 11 Acres




PHOTO:

COMMENTS:

Photographer Facing:
Negative File Number:
Photographer:
Negative on file with:

SURVEYOR: L. Monroe DATE: Dec. 82

1. STYLE _____	BUILDING TYPE _____	date
2. # STORIES <u>2½</u>	DIMENSIONS <u>25 x 50</u>	BAYS <u>Irreg.</u> FORM <u>Rectangular</u>
3. FOUNDATION <u>New block</u>	4. STRUCTURE <u>Balloon</u>	
5. WALLS: Sheathing <u>Clapboard</u>		Ornamentation <u>Cornerboards, frieze</u>
6. ROOF: Type <u>Cross gable</u>		Sheathing <u>Asphalt</u>
Dormers/Cupolas _____		Details _____
7. CHIMNEYS: # <u>2</u> Location <u>Brick interior</u>		Materials _____
Description <u>Stove corbel</u>		
8. EAVES TREATMENT: <u>Lateral Molded cornice, boxed, projecting with returns.</u>		
Gable End _____		
9. WINDOWS: Placement <u>Irregular</u>		Shape <u>Rectangular</u> Sash <u>2/2</u>
Surrounds <u>Plain boards with 2nd story small cape</u>		
10. ENTRIES: MAIN: Location <u>Left wing; porch</u>		Door <u>Single lite victorian panel</u>
Surround: Flanked <u>Simple board surrounds</u>		Topped <u>4 horizontal panels.</u>
Framed _____		
OTHERS: # _____ Location _____		Surrounds _____
Shed roof enclosed porch supported by clapboard parapet on centerblock foundation		
Front shed roof entry porch with square posts		
11. PORCHES/HOODS: # _____ Style/Roof type _____		
Location(s) _____		Supports _____
Other Features _____		
12. BAY WINDOWS/TOWERS: # <u>1</u> Location <u>Hip roof</u>		Stories _____ Shape <u>rec.</u>
Description(s) <u>Molded surrounds</u>		
13. ELLS/WINGS: # <u>1</u> letter <u>on map</u>		Stories A _____ B _____ C _____
Description(s) <u>ell and garage, same as main block</u>		Bays A _____ B _____ C _____
14. STOREFRONTS: Configuration _____		
Doors _____		Windows _____
Materials/Details _____		Signage _____

SITE DESCRIPTION/SURROUNDING ENVIRONMENT		
15. RELATED STRUCTURES # <u>0</u> Type _____		Description _____
16. LANDSCAPE FEATURES: Built _____		
Natural _____		
17. CONTEXT: <u>Surrounded by pasture and woods nearby, rural.</u>		

SIGNIFICANCE		
18. ARCHITECTURAL IMPORTANCE/INTEGRITY <u>While unusual in its present location, this well-developed Victorian structure would have appeared appropriate in its original in-town setting.</u>		
19. SITE INTEGRITY <u>Moved when Rte. 125 was established.</u>		
20. HISTORIC ASSOCIATIONS _____		

REFERENCES		
MAP DATA <u>1892: A. C. Chase</u>		