

CULTURAL RESOURCES SURVEY FORM

TOWN: Kingston COUNTY: Rockingham

SURVEY NUMBER: 163A

COMMON NAME: Dube House

HISTORIC NAME: School House

LOCATION:

OWNER: Thomas & Janice Dube  
70 Exeter Rd, Kingston, NH

ADDRESS:

MAP & PARCEL#: R-38 2

DATE: c.1887

SOURCE: Inspection

STYLE: Vernacular

UTM: Z /E /N

USGS QUAD:

FUNCTIONAL TYPE: School House

PRESENT USE: Residence

ARCHITECT/BUILDER:

CONDITION: Exc \_\_\_ Good \_\_\_ Fair \_\_\_ Poor \_\_\_ Ruins \_\_\_

INTEGRITY: Original Site \_\_\_ Moved \_\_\_  
Date \_\_\_

Major Alterations & Date:  
Many, date unknown

LEVEL/SIGNIFICANCE: Natl \_\_\_ State \_\_\_ Local \_\_\_ X

BOUNDARY AND ACREAGE DESCRIPTION: 1.3 Acres




PHOTO:

COMMENTS:

Photographer Facing:

Negative File Number:

Photographer:

Negative on file with:

SURVEYOR: L. Monroe DATE: Dec.82

1. STYLE _____	BUILDING TYPE _____	date _____
2. # STORIES <u>1½</u> DIMENSIONS <u>20 x 20</u>	BAYS _____ FORM _____	
3. FOUNDATION _____	4. STRUCTURE _____	
5. WALLS: Sheathing _____	Ornamentation _____	
6. ROOF: Type <u>Gable</u>	Sheathing <u>Vinyl siding</u>	
Dormers/Cupolas _____	Details _____	
7. CHIMNEYS: # _____	Location _____	Materials _____
Description _____		
8. EAVES TREATMENT: Lateral _____		
Gable End _____		
9. WINDOWS: Placement _____	Shape _____	Sash _____
Surrounds _____		
10. ENTRIES: MAIN: Location _____	Door _____	
Surround: Flanked _____	Topped _____	
Framed _____		
OTHERS: # _____	Location _____	Surrounds _____
11. PORCHES/HOODS: # _____	Style/Roof Type _____	
Location(s) _____	Supports _____	
Other Features _____		
12. BAY WINDOWS/TOWERS: # _____	Location _____	Stories _____
Description(s) _____		Shape _____
13. ELLS/WINGS: # _____	letter on map _____	Stories A _____ B _____ C _____
Description(s) _____		Bays A _____ B _____ C _____
14. STOREFRONTS: Configuration _____	Windows _____	
Doors _____	Materials/Details _____	
	Signage _____	

**SITE DESCRIPTION/SURROUNDING ENVIRONMENT**

15. RELATED STRUCTURES # _____	Type _____	
Description _____		
16. LANDSCAPE FEATURES: Built _____		
Natural _____		
17. CONTEXT:		

**SIGNIFICANCE**

18. ARCHITECTURAL IMPORTANCE/INTEGRITY	<u>Original school built of brick; in disrepair 1876; replaced 1887. No particular architectural significance. Historically important as one of the district schools in Kingston.</u>
19. SITE INTEGRITY	
20. HISTORIC ASSOCIATIONS	<u>School house</u>

**REFERENCES**

Kingston Historic Advisory Committee; interviews w/members, Spring 1980

MAP DATA 1856: Schoolhouse 1892: Schoolhouse