HISTORIC PRESERVATION ASSISTANCE PROJECT Strafford Rockingham Regional Council

1 Water Street, Exeter, New Hampshire Phone: (603) 778-0885

TOWN: Kingston COUNTY: Rockingham SURVEY NUMBER: 53 * COMMON NAME: Harlow House HISTORIC NAME: Chase's Carriage Shop LOCATION: west side of Main St., .50 miles North of Main & Depot OWNER: Carolyn Harlow ADDRESS: Kingston, NH. 196 Main St. MAP & PARCEL #: R-34/39 DATE: c. 1770 SOURCE: Inspection Vernacular STYLE:

UTM: Z 19 /E 332650 /N 4756375

USGS QUAD: Haverhill Quad 15' Series

FUNCTIONAL TYPE: Mechanic's Shop

PRESENT USE: Residential


ARCHITECT/BUILDER: Unknown

CONDITION: Exc. Good Fair Poor x Ruins

INTEGRITY: Original Site x Moved
(When:)

Major alterations & date: Remodelled

LEVEL/SIGNIFICANCE: Natl State Local X





Description of View: Front-northeast
Side-southeast

Photographer: Scott Novak Negative with: S.R.R.C.

Negative File Number: K-80-5c/28-28A

ADDITIONAL ARCHITECTURAL AND STRUCTURAL DESCRIPTION:

The Harlow House is a vernacular house which was altered by later remodeling. The center entry has a multi-panel and multi-light door sheltered by a small gabled door hood. Most of the windows are new, with six-over-six sash. A new oriel window with sidelights is located on the gable end. The medium-pitch roof has close raking and lateral eaves and is topped by a narrow central chimney with a corbelled cap. The main block rests on a fieldstone foundation.

A' 2-story, gable-roofed ell extends to the south and west. It has clapboard siding. the same cornice treatment as the main block, and rests on a fieldstone foundation. To the northwest is a 1-story, gable-roofed wing with clapboard siding and new arched windows.

RELATED STRUCTURES AND CONTEXT: There is a separate 11/2-story, gable-roofed barn located to the north. It has clapboard siding, large double doors with sidelights and an oriel window on its front facade. An attached shed extends to the south of the barn. A separate shed is located to the northwest.

BOUNDARY AND ACREAGE DESCRIPTION: 3.2 acres bounded to the N-Rte. 125, S-Magnosan. E-Main Street, W-Levesque.

REFERENCES:

. 1856 Map 1892 Map

STATEMENT OF SIGNIFICANCE (Evaluation & Historical Associations):

Site 53 survives as an example of late 18th century agricultural complex. In deteriorating condition, this building is threatened by its own decomposition.

MAP DATA: 1856: Mechanic's Shop

1892: Carriage Shop

1856-Blacksmith MAP DATA 1892-Carriage Shop

SURROUNDING ENVIRONMENT: Open Land Woodland Scattered Bldgs X Moderately Built Up Densely Built Up Residential X Commercial Industrial Agricultural Roadside Strip Development Other

Recorded By: Herb Bubert

Scott Novak

Date: 12/20/79

