

HISTORIC PRESERVATION ASSISTANCE PROJECT

Strafford Rockingham Regional Council

1 Water Street, Exeter, New Hampshire


Phone: (603) 778-0885

TOWN: Kingston	COUNTY: Rockingham	UTM: Z 19 / E 332175 / N 4755800
SURVEY NUMBER: 78 *		USGS QUAD: Haverhill Quad 15' Series
COMMON NAME:		FUNCTIONAL TYPE:
HISTORIC NAME:		PRESENT USE:
LOCATION: West side of Church St. .15 miles south of inter. Church & Cottage		ARCHITECT/BUILDER: Unknown
OWNER: Cecil Cross		CONDITION: Exc. <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Ruins <input type="checkbox"/>
ADDRESS: 14 Church St., Kingston, NH		INTEGRITY: Original Site <input type="checkbox"/> Moved <input type="checkbox"/> (When: <input type="checkbox"/>)
MAP & PARCEL #: U-10, plot 16		Major alterations & date: <input type="text"/>
DATE: c. 1900		LEVEL/SIGNIFICANCE: Natl <input type="checkbox"/> State <input type="checkbox"/> Local <input type="checkbox"/>
SOURCE: Herb Buhert & Scott Novak		
STYLE: None		

GENERAL DESCRIPTION: Structural System

- FOUNDATION: Stone ☐ Brick ☐ Concrete ☒ Concrete Block ☐
- WALL STRUCTURE: Wood Frame ☐ Post & Beam ☐ Ballon Frame ☒ Other ☐
Load Bearing Masonry ☐ Stone ☐ Brick ☐ Concrete Block ☐ Other ☐
Metal ☐ Iron ☐ Steel ☐ Other ☐
- WALL COVERING: Clapboard ☐ Wood Shingle ☐ Board & Batten ☐ Shiplap ☐ Aluminum ☐
Novelty ☐ Stucco ☐ Stone ☐ Brick ☐ Sheet Metal ☐ Asphalt Shingles ☒ Vinyl ☐
Asphalt Sheeting ☐ Composite Board ☐ Other ☐
- ROOF SHEATHING: Wood Shingle ☐ Asphalt Shingle ☒ Standing Seam Tin ☐ Slate ☐
Pressed Metal ☐ Sheet Metal ☐ Rolled Asphalt ☐ Other ☐
- ENGINEERING STRUCTURE:
- OTHER:
of Stories 1 1/2 # of Bays 3 Approx. Dimensions 30' x 45'
Roof Style: Gable ☒ Hip ☐ Gambrel ☐ Flat ☐ Shed ☐ Mansard ☐ Jerkinhead ☐
Monitor ☐ Sawtooth ☐ Other ☐
Appendages: Porches ☐ Towers ☐ Dormers ☐ Bay Windows ☐ Ells ☐ Chimneys 1
Wings ☐ Cupolas ☐ Sheds ☐ Garage ☐ Other ☐
Entry Location: Center ☒ Sidehall ☐ Other ☐


MAP (Indicate North in circle):



79

CHURCH STREET

PHOTO

Description of View: Front-north
Side-northPhotographer: Scott Novak
Negative with: S.R.R.C.
Negative File Number: K-80-3c/18-18A

ADDITIONAL ARCHITECTURAL AND STRUCTURAL DESCRIPTION:

1½ story frame building.

Gable roof with simple overhangs.

Street face is center door with multipaned glass topped by small gable roof doorhood supported by truss brackets. Flanked by small square windows 2/1 with plain surrounds. Same experience on lateral side except major entry has double leaf doors with shed roof, doorhood supported by truss brackets and giving forth onto small deck.

RELATED STRUCTURES AND CONTEXT:

BOUNDARY AND ACREAGE DESCRIPTION: .7 acres

REFERENCES:

Kingston Historic Advisory Committee; interviews w/members, Spring 1980

STATEMENT OF SIGNIFICANCE (Evaluation & Historical Associations):

This simple frame structure is one of the only commercial units surviving in this section of the district.

Used as a salesroom for furniture and rugs. Vacant for several years.

SURROUNDING ENVIRONMENT: Open Land__ Woodland__ Scattered Bldgs__ Moderately Built Up__
Densely Built Up__ Residential ☒ Commercial__ Industrial__ Agricultural__
Roadside Strip Development__ Other__

Recorded By: Herb Bubert

Date: 12/27/73

