## HISTORIC PRESERVATION ASSISTANCE PROJECT

Strafford Rockingham Regional Council

1 Water Street, Exeter, New Hampshire

Phone: (603) 778-0885

TOWN: Kingston COUNTY: Rockingham SURVEY NUMBER: COMMON NAME: Leate House H. Goodwin House HISTORIC NAME: LOCATION: W side of Rte. 125, .09 miles N of the inter of West Shore &-Rte. 125 OWNER: George & Kathleen Leate, Jr. ADDRESS: .90 Rte. 125, MAP & PARCEL #: R-8/39 DATE: c. 1770 SOURCE: Inspection STYLE: Georgian

UTM: Z 19 /E 330175 /N 4750050 USGS QUAD: Haverhill Quad 15' Quad Series FUNCTIONAL TYPE: Residential PRESENT USE: Residential ARCHITECT/BUILDER: J. Alfred Lyford CONDITION: Exc. Good Fair XPoor Ruins INTEGRITY: Original Site X Moved (When: Major alterations & date: extensive interfor work ongoing 1980. LEVEL/SIGNIFICANCE: Natl State LocalX

GENERAL DESCRIPTION: Structural System

 FOUNDATION: Stone X Brick Concrete Concrete Block
 WALL STRUCTURE: Wood Frame Post & Beam X Ballon Frame Other Load Bearing Masonry Stone Brick Concrete Block Other

Other

3. WALL COVERING: Clapboard X Wood Shingle Board & Batten Shiplap Aluminum Novelty Stucco Stone Brick Sheet Metal Asphalt Shingles Vinyl Asphalt Sheeting Composite Board Other

4. ROOF SHEATHING: Wood Shingle Apshalt Shingle X Standing Seam Tim Slate Pressed Metal Sheet Metal Rolled Asphalt Other

5. ENGINEERING STRUCTURE:


6. OTHER:

# of Stories 11/2 # of Bays 3x3 Approx. Dimensions 25' x 35' Roof Style: Gable X Hip Gambrel Flat Shed Mansard Jerkinhead

Monitor Sawtooth Other

Appendages: Porches 1 Towers Dormers Bay Windows Ells Chimneys 1

Wings Cupolas Sheds 1 Garage Other Oriel window
Entry Location: Center Sidehall Other Offset







Description of View:

Front-east Side-south

Photographer: Scott Novak Negative with: S.R.R.C.

Negative File Number: K-80-6-c/35-35A

## ADDITIONAL ARCHITECTURAL AND STRUCTURAL DESCRIPTION:

The Leate House is a 1/2-story Central chimney Georgian style structure. The offset entry has a 4-panel door with two lights. There is a large picture window on the front facade, and the other windows are one-over-one. The modified gable roof is topped by a large central chimney with a corbel cap. Cornice treatment consists of close raking eaves and boxed lateral eaves.

A 1-story, gable-roofed, enclosed porch to the north has a 4-panel door with two lights, clapboard siding, and a concrete block foundation. It has an oriel window on the northeast side.

RELATED STRUCTURES AND CONTEXT: A separate 1-story, gable-roofed shed to the north has clapboard siding, a vertical-board door, fixed 6-light windows and a fieldstone foundation.

BOUNDARY AND ACREAGE DESCRIPTION: 1.6 acres bounded to the N-Mill Pond, S-Burke, E-Rte. 125, W-Mill Pond, Burke.

## REFERENCES:

1856 Map 1892 Map

1856 Map H. Goodwin, 1892 Map Store

## STATEMENT OF SIGNIFICANCE (Evaluation & Historical Associations):

The architectural significance of the H. Goodwin House has been severely compromised by recent modifications, although it still makes an historic contribution.

Map Data: 1856: H. Goodwin

1892: Store

SURROUNDING ENVIRONMENT: Open Land Woodland Scattered Bldgs Moderately Built Up\_ Densely Built Up\_ Residential Commercial Industrial Agricultural\_ Roadside Strip Development\_Other\_

Recorded By: Scott Novak

Herb Bubert

Date: 2/8/80

