HISTORIC PRESERVATION ASSISTANCE PROJECT Strafford Rockingham Regional Council

1 Water Street, Exeter, New Hampshire

Phone: (603) 778-0885

TOWN: Kingston COUNTY: Rockingham
SURVEY NUMBER: 150
COMMON NAME: Magnuson House
HISTORIC NAME: M. Davis House
LOCATION: East side of Rte. 125, .40 miles North of intersection of Rte. 107.
OWNER: Conrad Magnuson ADDRESS: 261 Rte. 125, Kingston, NH
MAP & PARCEL #: R-40/7
DATE: c. 1880
SOURCE: Inspection
STYLE: Greek Revival

UTM: Z 19 /E 331975 /N 4757575 USGS QUAD: Haverhill Quad 15' Series FUNCTIONAL TYPE: Farmhouse PRESENT USE: Residential ARCHITECT/BUILDER: Unknown CONDITION: Exc. Good X Fair Poor Ruins INTEGRITY: Original Site X Moved (When: On site of earlier structure? Major alterations & date: Much remodeling c. 1920. LEVEL/SIGNIFICANCE: Natl State Local X

GENERAL DESCRIPTION: Structural System

1. FOUNDATION: Stone X Brick Concrete Concrete Block

2. WALL STRUCTURE: Wood Frame Post & Beam Ballon Frame X Other Load Bearing Masonry Stone Brick Concrete Block Other Metal Iron Steel Other Other


3. WALL COVERING: Clapboard X Wood Shingle Board & Batten Shiplap Aluminum Novelty Stucco Stone Brick Sheet Metal Asphalt Shingles Vinyl Asphalt Sheeting Composite Board Other

4. ROOF SHEATHING: Wood Shingle Apshalt Shingle X Standing Seam Tim Slate Pressed Metal Sheet Metal Rolled Asphalt Other

5. ENGINEERING STRUCTURE:

6. OTHER:

of Stories 11/2 # of Bays 2x4 Approx. Dimensions 17' x 21' Roof Style: Gable x Hip Gambrel Flat Shed Mansard Jerkinhead Monitor Sawtooth Other Appendages: Porches 1 Towers Dormers Bay Windows Ells 1 Chimneys Wings Cupolas Sheds 6 Garage Other Entry Location: Center Sidehall % Other



РНОТО



Description of View: Front-south

Side-west

Photographer: Scott Novak Negative with: S.R.R.C.

Negative File Number: K-80-11c/28-28A

ADDITIONAL ARCHITECTURAL AND STRUCTURAL DESCRIPTION:

The Magnusun House is a 1%-story late nineteenth century vernacular structure. The 4-panelled sidehall entry door is topped by a slightly projecting doorhood. Windows have two-over-two sash. Eaves treatment consists of a boxed cornice with gable-end returns.

A 1-story shed-roofed porch on the south elevation is supported by square columns. A 1-story, gable-roofed ell rests on a cement foundation. It has clapboard siding, a 4-panelled door, two-over-two windows, a boxed cornice, and one chimney.

RELATED STRUCTURES AND CONTEXT: An attached 1½-story, gable-roofed barn has clapboard siding, one-over-one windows, and a 4 panelled door containing one large light.

Several separate sheds are all attached to one another.

BOUNDARY AND ACREAGE DESCRIPTION: .17 acres bounded to the N-Magnusson, S-Martin, Magnusson, E-Magnusson, W-Route 125.

REFERENCES:

Kingston Historic Advisory Committee; interviews w/members, Spring 1980

1856

39

1892 Map

STATEMENT OF SIGNIFICANCE (Evaluation & Historical Associations):

This structure presently appears as a late 19th century vernacular house. Map data indicates an earlier structure belonging to M. Davis on site. Interior inspection might prove to be Greek Revival as early as c.1840.

MAP DATA: 1856: M. Davis 1892: A. F. Davis

SURROUNDING ENVIRONMENT: Open Land Woodland Scattered Bldgs Moderately Built Up_ Densely Built Up_ Residential Commercial Industrial Agricultural

Roadside Strip Development Other

Recorded By: Scott Novak

Herb Bubert

Date: 4/7/80

